The contractor is responsible for checking dimensions, juliances and elementes. Any discrepancy to be verified with the Architect before proceeding with the works. Whenever the littless as laten is convent by diserings to different scales the larger scale disering is but worked to. Over its scale drawing. Figured dimensions to be modeled to in all cases.

